



Dougherty Forestry Mfg.

(DFM reserves the right to change pricing without notice)

2022 Parts Pricing

(Updated 1-1-2023)

TURBOSAW CUTTING DISC REPLACEMENT PARTS



TS5125 Mastodon Cutting Tooth, Carbide, 1.25" x 1.25":	\$30.63 ea.
B1043, TS3/TS5 Holding Bolt (B1043):	\$3.14 ea.
W1044, TS3/TS5 X5 Double Washer:	\$1.55 ea.
B3429, TS3/S5 Weld-in Backing Block:	\$8.33 ea.
C3063, 30" Cutting Disc, Weld-On Teeth, .375" thick, 6 teeth:	\$760.58 ea.

TURBOSAW CUTTING DISC (disc with backing blocks only)

D30153, 30" Cutting Disc, TS5 System, .375" thick, 15 teeth:	\$557.00 ea.
D30105, 30" Cutting Disc, TS5 System, .5" thick, 10 teeth:	\$742.00 ea.
D30155, 30" Cutting Disc, TS5 System, .5" thick, 15 teeth:	\$742.00 ea.
D32105, 32" Cutting Disc, TS5 System, .5" thick, 10 teeth:	\$891.00 ea.
D34105, 34" Cutting Disc, TS5 System, .375" thick, 10 teeth:	\$668.00 ea.
D30255, 30" RS Multi-Surface Cutting Disc, TS5 System, .5" thick, 25 teeth:	\$742.00 ea.
D34255, 34" RS Multi-Surface Cutting Disc, TS5 System, .5" thick, 25 teeth:	\$891.00 ea.



MASTODON MULCHER REPLACEMENT PARTS

M1018, Mastodon Planer Tooth, 2 Bolt System:	\$76.16 ea.
M1018H, Mastodon Planer Tooth, 2 Bolt System with Hard-facing:	\$96.17 ea.
M1019, Mastodon Hammer Tooth, 2 Bolt System:	\$89.00 ea.
M1019HH, Mastodon Hammer Tooth, 2 Bolt System with Hard-facing:	\$109.00 ea.
W1045, Mastodon Tooth Lock Washer:	\$1.44 ea.
B1047, Mastodon Tooth Holding Bolt:	\$1.77 ea.
MH1020, Mastodon Tooth Weld-On Holder:	\$37.90 ea.